

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

| | | | | | | | | | | |
|---|---|--------------------------|----|---|---|------------|-------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| Date of Thorough Examination: | | 14 April 2026 | | Report number: | | 17833/0014 | | | | |
| Name and Address for whom the thorough examination was made: | | | | Address of premises at which the examination was made: | | | | | | |
| FCC Recycling (UK) Limited Greatmoor EFW Greatmoor Road Woodham Aylesbury HP18 0QE | | | | All Sites - Level 08 | | | | | | |
| Identification of the equipment | Description of the equipment | | | Safe Working Load | Date of last thorough examination | | | | | |
| 1 SMF10 AE001 - 18866-41 | RUNWAY BEAM COMPRISING OF HEA240 EUROPEAN SECTION, 2.5 METRES LONG INCLUDING A 0.5 METRE CANTILEVER ONE END, SUPPORTED FROM STRUCTURAL STEELWORK AT 1.3 METRE CENTRES SWF ELECTRIC CHAIN HOIST MODEL : CB 045.1P-N SERIAL NO. 1517104003 | | | 0.5t | 10/03/2025 | | | | | |
| | | | | Examination carried out : - | | | | | | |
| Is this the first examination after installation or assembly at a new site or location? | YES | <input type="checkbox"/> | NO | <input checked="" type="checkbox"/> | Within an interval of 6 months? | YES | <input type="checkbox"/> | NO | <input checked="" type="checkbox"/> | |
| | | | | | Within an interval of 12 months? | YES | <input checked="" type="checkbox"/> | NO | <input type="checkbox"/> | |
| If the answer to the above question is YES, has the equipment been installed correctly? | YES | <input type="checkbox"/> | NO | <input type="checkbox"/> | In accordance with an examination scheme? | YES | <input type="checkbox"/> | NO | <input checked="" type="checkbox"/> | |
| | | | | | After the occurrence of exceptional circumstances? | YES | <input type="checkbox"/> | NO | <input checked="" type="checkbox"/> | |
| Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) | | | | | | | | | | |
| There is a oil leak from the hoist unit. | | | | | | | | | | |
| Is the above an existing or imminent danger to persons *Note-This is a reportable defect | | | | | | YES | <input type="checkbox"/> | NO | <input type="checkbox"/> | |
| Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) | | | | | YES by: | | | NO | <input type="checkbox"/> | |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above: (If none state NONE) | | | | | | | | | | |
| This needs to be investigated further. | | | | | | | | | | |
| Particulars of any tests carried out as part of the examination: (If none state NONE) | | | | | | | | | | |
| NONE | | | | | | | | | | |
| IS THIS EQUIPMENT SAFE TO USE? | | | | | | | YES | <input checked="" type="checkbox"/> | NO | <input type="checkbox"/> |

Name & Qualifications of person making this report:

Neil Dix-Peek
LEEA Qualified
Company Approved Technician



Name of person authenticating this report:

Graham Bramley



Latest date by which next thorough examination must be carried out:

14/04/2027

Name and address of employer of persons making and authenticating this report:

Bramley Engineering, 22 Eden Way, Pages Industrial Park, Leighton Buzzard, Bedfordshire, LU7 4TZ.