

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination:		11 March 2025		Report number:		16752/0047					
Name and Address for whom the thorough examination was made:				Address of premises at which the examination was made:							
FCC Recycling (UK) Limited Greatmoor EFW Greatmoor Road Woodham Aylesbury HP18 0QE				FCC Recycling (UK) Limited, Level 00							
Identification of the equipment	Description of the equipment			Safe Working Load	Date of last thorough examination						
0 SMJ21 AE002 - 18866-67	RUNWAY BEAM COMPRISING OF IPE120 EUROPEAN SECTION, 1.7 METRES LONG INCLUDING A 0.7 METRE CANTILEVER ONE END, SUPPORTED FROM STRUCTURAL STEELWORK AT 1.0 METRE CENTRES SWF COMBINED HAND CHAIN BLOCK AND TROLLEY SERIAL NO. 2247312220			0.15t	25/04/2024						
				Examination carried out : -							
Is this the first examination after installation or assembly at a new site or location?		YES	☐	NO	☒	Within an interval of 6 months?		YES	☐	NO	☒
						Within an interval of 12 months?		YES	☒	NO	☐
If the answer to the above question is YES, has the equipment been installed correctly?		YES	☐	NO	☐	In accordance with an examination scheme?		YES	☐	NO	☒
						After the occurrence of exceptional circumstances?		YES	☐	NO	☒
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) The chain block is severely corroded.											
Is the above an existing or imminent danger to persons *Note-This is a reportable defect								YES	☒	NO	☐
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)						YES by:			NO	☒	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: (If none state NONE) The chain block must be replaced.											
Particulars of any tests carried out as part of the examination: (If none state NONE) NONE											
IS THIS EQUIPMENT SAFE TO USE?								YES	☐	NO	☒

Name & Qualifications of person making this report:

Neil Dix-Peek
LEEA Qualified
Company Approved Technician

Name of person authenticating this report:

Ashleigh Trotter

Latest date by which next thorough examination must be carried out:

A Trotter

Name and address of employer of persons making and authenticating this report:

Bramley Engineering, 22 Eden Way, Pages Industrial Park, Leighton Buzzard, Bedfordshire, LU7 4TZ.