

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination:		10 March 2025		Report number:		16752/0034						
Name and Address for whom the thorough examination was made:				Address of premises at which the examination was made:								
FCC Recycling (UK) Limited Greatmoor EFW Greatmoor Road Woodham Aylesbury HP18 0QE				FCC Recycling (UK) Limited, Level 04								
Identification of the equipment	Description of the equipment			Safe Working Load	Date of last thorough examination							
1 SMD41 AE010 18866-33	RUNWAY BEAM COMPRISING OF IPE240 EUROPEAN SECTION, 2.5 METRES LONG SUPPORTED FROM STRUCTURAL STEELWORK AT EACH END SWF PUSH GIRDER TROLLEY SERIAL NO. CHB19954-110167			0.5t	25/04/2024							
				Examination carried out : -								
Is this the first examination after installation or assembly at a new site or location?		YES	☐	NO	☒	Within an interval of 6 months?		YES	☐	NO	☒	
						Within an interval of 12 months?		YES	☒	NO	☐	
If the answer to the above question is YES, has the equipment been installed correctly?		YES	☐	NO	☐	In accordance with an examination scheme?		YES	☐	NO	☒	
						After the occurrence of exceptional circumstances?		YES	☐	NO	☒	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)												
The gap between the trolley wheels and the beam flange is too large (3mm)												
Is the above an existing or imminent danger to persons *Note-This is a reportable defect									YES	☐	NO	☒
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)						YES by:	10/06/2025		NO	☐		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: (If none state NONE)												
The beam trolley needs to be adjusted to the correct spacing.												
Particulars of any tests carried out as part of the examination: (If none state NONE)												
NONE												
IS THIS EQUIPMENT SAFE TO USE?									YES	☒	NO	☐

Name & Qualifications of person making this report:

Neil Dix-Peek
LEEA Qualified
Company Approved Technician

Name of person authenticating this report:

Ashleigh Trotter

Latest date by which next thorough examination must be carried out:

10/03/2026

Name and address of employer of persons making and authenticating this report:

Bramley Engineering, 22 Eden Way, Pages Industrial Park, Leighton Buzzard, Bedfordshire, LU7 4TZ.