

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination:		24 July 2026		Report number:		17014/0015					
Name and Address for whom the thorough examination was made:				Address of premises at which the examination was made:							
FCC Recycling (UK) Limited Greatmoor EFW Greatmoor Road Woodham Aylesbury HP18 0QE				All Sites - Level 00							
Identification of the equipment	Description of the equipment			Safe Working Load	Date of last thorough examination						
0 SMJ21 AE002 - 18866-67	RUNWAY BEAM COMPRISING OF IPE120 EUROPEAN SECTION, 1.7 METRES LONG INCLUDING A 0.7 METRE CANTILEVER ONE END, SUPPORTED FROM STRUCTURAL STEELWORK AT 1.0 METRE CENTRES SWF COMBINED HAND CHAIN BLOCK AND TROLLEY SERIAL NO. 22473122220			0.15t	25/04/2024						
				Examination carried out : -							
Is this the first examination after installation or assembly at a new site or location?		YES	☐	NO	☒	Within an interval of 6 months?		YES	☐	NO	☒
						Within an interval of 12 months?		YES	☒	NO	☐
If the answer to the above question is YES, has the equipment been installed correctly?		YES	☐	NO	☐	In accordance with an examination scheme?		YES	☐	NO	☒
						After the occurrence of exceptional circumstances?		YES	☐	NO	☒
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)											
NONE											
Is the above an existing or imminent danger to persons *Note-This is a reportable defect								YES	☐	NO	☐
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)						YES by:			NO	☐	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: (If none state NONE)											
Particulars of any tests carried out as part of the examination: (If none state NONE)											
NONE											
IS THIS EQUIPMENT SAFE TO USE?								YES	☒	NO	☐

Name & Qualifications of person making this report:

Aaron Lovell
LEEA Qualified
Company Approved Technician

Name of person authenticating this report:

Graham Bramley

Latest date by which next thorough examination must be carried out:

24/07/2027

Name and address of employer of persons making and authenticating this report:

Bramley Engineering, 22 Eden Way, Pages Industrial Park, Leighton Buzzard, Bedfordshire, LU7 4TZ.